




NEW "Super-Seal™" Packing

The stuffing box is perhaps the most important piece to your artificial lift surface hookup from the standpoint, it is your surface **SEAL**. The most important component to the stuffing box, sealing, is the packing inside the stuffing box. WSI engineering continues to set the bar with new developmental materials to meet the demands for ever-changing well conditions.

By working with rubber manufacturers and field testing new designs, WSI wants to make certain that our packing stands up to stringent durability and performance standards expected by our customers.



Material	Max. % H ₂ S	Max. % CO ₂	Max. Temperature
Super-Seal "Soft"	2%	Not Recommended	160°F (71°C)
Super-Seal "HSN"	10%	20%	325°F (163°C)
Super-Seal "KB"	10%	10%	500°F (260°C)

Order your WSI stuffing box with "Super-Seal"
installed from the factory

Important Note: The guidelines on this page are for general purposes only and should not be used as the sole determining factor for packing material selection. Each down hole condition is different and must be addressed on a case-by-case basis to determine the best material solution for your particular well condition.

"Make Your Connection with WSI"